



Partner Training



Gearbox for trainings

GPV 306



GPV 442



GPV 570



EH 802 | 804



EH 921 | 922



EF 901



Training Matrix

Content							
Turbine Platform	Gear unit	Inspection	HSS exchange	IMS exchange	Mech. pump exchange	Pitch pipe repair (bearing exchange)	Repair oil system & repair/exchange electrical comp.
Vestas V112	GPV570	Yes	Yes	3rd stage complete	Yes	Yes	No
Vestas V112/117/126/136	EH921/EH922	Yes	Yes	3rd stage complete	No	Yes	Oiltube, Manifold
Vestas V80/90 Gamesa G80	GPV442	Yes	Yes	Yes	Yes	Yes	Yes
	EH802/EH804	Yes	Yes	No, only generator side bearing	Yes	Yes	No
Vestas V52 Gamesa G52	GPV306	Yes	Yes	No	Yes	Yes	Yes
Vestas V90	EF901	Yes	Possible (only 3rd stage ex. recommended)	3rd stage complete	No	No	Yes